
LAFAYETTE BUILDING PERIMETER SECURITY IMPROVEMENTS

WASHINGTON, DC

ENVIRONMENTAL ASSESSMENT



AUGUST 2007

TABLE OF CONTENTS

1.0	PURPOSE AND NEED	
1.1	Introduction.....	1-1
1.2	Background.....	1-3
1.3	Purpose and Need for the Proposed Action.....	1-4
1.4	Public Involvement and Agency Coordination.....	1-5
1.4.1	Public/Agency Coordination and Scoping.....	1-5
1.4.2	Public/Agency Comments on the EA.....	1-5
1.5	Environmental Issues Considered.....	1-6
2.0	ALTERNATIVES	
2.1	Introduction.....	2-1
2.2	Perimeter Security Alternative A.....	2-1
2.3	Perimeter Security Alternative B.....	2-4
2.4	No Action Alternative.....	2-7
3.0	AFFECTED ENVIRONMENT	
3.1	Cultural Resources.....	3-1
3.1.1	Historic Resources.....	3-2
3.1.2	Visual Resources.....	3-13
3.2	Land Use and Planning Policies.....	3-19
3.2.1	Land Use.....	3-19
3.2.2	Planning Policies.....	3-19
3.3	Vegetation.....	3-26
3.4	Transportation.....	3-27
3.4.1	Vehicular Circulation and Access.....	3-27
3.4.2	Parking.....	3-29
3.4.3	Pedestrian Circulation.....	3-30
3.5	Utilities and Infrastructure.....	3-31
4.0	ENVIRONMENTAL CONSEQUENCES	
4.1	Cultural Resource Impacts.....	4-1
4.1.1	Historic Resource Impacts.....	4-1
4.1.2	Visual Resource Impacts.....	4-6
4.2	Land Use and Planning Policy Impacts.....	4-12
4.2.1	Land Use Impacts.....	4-12
4.2.2	Planning Policy Impacts.....	4-13
4.3	Vegetation Impacts.....	4-15
4.4	Transportation Impacts.....	4-17
4.4.1	Vehicular Circulation Impacts.....	4-17
4.4.2	Parking Impacts.....	4-21
4.4.3	Pedestrian Circulation Impacts.....	4-22
4.5	Utilities and Infrastructure Impacts.....	4-24

5.0 CUMULATIVE IMPACTS

5.1	Cumulative Impacts.....	5-1
-----	-------------------------	-----

6.0 APPENDIX

6.1	Sources
6.2	Preparers
6.3	Notification List

FIGURES

Figure 1-1	Lafayette Building Project Site and Surrounding Area.....	1-2
Figure 1-2	Southwest Corner and West Elevation of Lafayette Building with Entrance at Vermont Avenue, NW.....	1-3
Figure 2-1	Perimeter Security Alternative A.....	2-3
Figure 2-2	Perimeter Security Alternative B.....	2-6
Figure 3-1	Area of Potential Effects.....	3-1
Figure 3-2	Lafayette Building Entrance on Vermont Avenue, NW showing temporary security planters.....	3-3
Figure 3-3	West Elevation of Lafayette Building (view north on Vermont Ave) showing mature trees.....	3-3
Figure 3-4	Southwest Corner of Lafayette Building (facing Lafayette Park).....	3-4
Figure 3-5	East Elevation on 15 th Street, NW (looking south from 15 th and I).....	3-4
Figure 3-6	Entrance to Alley on 15 th Street, NW.....	3-5
Figure 3-7	Garage Entrance on H Street, NW.....	3-5
Figure 3-8	1791 Plan of the City of Washington (L'Enfant Plan).....	3-6
Figure 3-9	15 th Street, NW at H Street, NW Looking North with Lafayette Building on far left.....	3-7
Figure 3-10	Union Trust Company Building.....	3-8
Figure 3-11	The Shoreham Building (now the Sofitel Hotel).....	3-9
Figure 3-12	Lafayette Square.....	3-10
Figure 3-13	Department of Veterans Affairs Headquarters Building (across Vermont Avenue, looking south).....	3-11
Figure 3-14	United Mine Workers Building (McPherson Square to right).....	3-12
Figure 3-15	Vermont Avenue at H Street, NW Looking to the North.....	3-13
Figure 3-16	Looking North on the Vermont Avenue Sidewalk.....	3-14
Figure 3-17	H Street, NW at Vermont Avenue Looking to the East.....	3-15
Figure 3-18	H Street, NW Looking East in Front of the Sofitel Hotel.....	3-16
Figure 3-19	15 th Street at I Street Looking to the South (Lafayette Building on right).....	3-17
Figure 3-20	15 th Street Sidewalk Looking to the North with McPherson Square in the Distance (Lafayette Building on left).....	3-17
Figure 3-21	I Street, NW looking to the West.....	3-18
Figure 3-22	The Sidewalk on I Street, NW Looking to the West.....	3-19
Figure 3-23	Line of Elm Trees on 15 th Street, NW.....	3-26

Figure 4-1 Simulation Showing Proposed Security Elements
at Corner of Vermont Avenue and H Streets.....4-7

Figure 4-2 View North on Vermont Avenue Showing
Conceptual Placement of New Trees and Curb.....4-9

Figure 5-1 Perimeter Security in the National Capital.....5-2

TABLES

Table 3-1 Existing Intersection Level of Service.....3-29